LAND APPLICATION OF BIOSOLIDS SITE INSPECTION FORM

GENERAL INFORMATION:				`E:	2/2/2006				
COUNTY: Westmoreland CONTRACTOR/MUNICIPALITY: Recyc Systems, Inc.									
NAME (OWNER/OPERATOR): William O. Sydnor / Ruby Presnall									
¥ ` /				ERMIT NO: VDHBUR 9					
FIELD NO: WMWOS – fields 23,24, 25				ACRES: 36.3, 35.3, 16.3					
OTHERS PRESENT: Fay Dove, Beth McDowell (Westmoreland Co.); Sonny Deal (RECYC)									
FIELD DATA/OBSERVATIONS:				TIME: 1:40PM					
WEATHER: Sunny, E wind				SOIL CONDITIONS: Moist					
BIOSOLIDS SOURCE: Blue Plains				BIOSOLIDS TYPE: lime stabilized					
SOIL pH: 6.0, 6.1, 6.3				SOLIDS CONTENT OF BIOSOLIDS (%): @28					
APPLICATION RATE: 21 / 18 / 14 WT/ac									
CROP AND EXPECTED YIELD: Corn									
LOAD TO DATE (WT): see monthly report									
BIOSOLIDS APPLIED: () LIQUID (x) DEWATERED									
MODE OF APPLICATION:	(x) SURFACE () SURFACE W/INCORP. (() INJECTION		
APPLICATION LIMITED	(X)	(X) NITROGEN (X) pH							
BY:									
() MAX. HYDRAULIC LOADING (LIQUID BIOSOLIDS)									
() MAX. SOLIDS LOADING (15 DRY TONS/ACRE)									
() OTHER (SPECIFY):									
FIELD OBSERVATIONS							<u>YES</u>	<u>NO</u>	
BUFFERS OBSERVED:							X		
UNIFORM APPLICATION:							X		
PROPER FIELD RECORDS:							X		
SIGNS OF RUNOFF:								X	
TRUCKS NON-SPILL/WATERTIGHT:						X			
CONDITION OF HAUL ROUTE SATISFACTORY:							X		
ODORS PRESENT:	() NO	ONE	(X) NORM	AL	() ABOVE		
						NORMAL*			
OVERALL CONDITION OF S	SITE:	(X)GOOD		() FAI	R	() POOR		

COMMENTS: (*explain):

Scott Haley (writer) received a telephone call from Fay Dove with the Westmoreland County Zoning Department. Mrs. Dove had received a complaint about odors at a biosolids application site from the owner of a small grocery/convenience store located to the north of the site. Writer met Mrs. Dove and Ms. McDowell at the County Office Building in Montross and then traveled to the site. Land application had been recently completed on the site, and odors were present but not strong.

Writer traveled to the store and spoke with the complainant. Complainant stated that wind had been blowing from the south which would have transported odors towards the store. At the time of the visit, wind had changed direction and was blowing from the east. Writer and county personnel could not detect biosolids odors at the store.

Complainant asked questions about runoff and if the surface applied biosolids must be incorporated. Writer explained that this site was a no-till crop field, and buffers had been observed to be in compliance with the regulations. Writer and county staff asked the complainant to call again if odor persisted.

Writer and county staff traveled to the current land application site to evaluate odor and spoke with the MES inspector, who stated that the pH of the biosolids had been testing in a range from 12.2 to 12.3. Odors at the current land application site were also considered to be normal.

COPIES: VDH - Div of Wastewater Engineering

Westmoreland County